



KONICA MINOLTA

光沢計 GM-268A 光沢計 GM-60A, 60CT, 60S ご使用前に

ご使用前に必ずお読みください

取扱説明書およびソフトウェアについて

本器の取扱説明書およびソフトウェアは、下記の製品サポートページからダウンロードできます。
ソフトウェア <https://www.konicaminolta.jp/instruments/support/download/color/index.html>
ハードウェア https://www.konicaminolta.jp/instruments/member/support_registration
説明をよく読んでお使いください。

安全に関する絵表示について

本書または製品に記載の警告や注意には、本器の誤った取り扱いによる事故を未然に防止するために、以下のようなマークを付けています。

- 安全に関する警告や注意の文章が記載されていることを示します。記載の文章をよく読んで、正しく安全にお使いください。
- 禁止の行為であることを示しています。絶対に行なわないでください。
- 禁止の行為であることを示しています。絶対に分解しないでください。
- 直流 (DC) を表しています。

安全の警告と注意

本器を使用するときは、必ず以下の事項を守り、正しくお使いください。また、取扱説明書は、よく読んだ上、いつでも見ることができる場所に大切に保管してください。他人へ本器を貸す或いは譲渡される際は、必ずこれらの説明書類も合わせてお渡しください。

警告 (取り扱いを誤ると、使用者が死亡または重傷を負う可能性が想定される場合)	
引火性・可燃性蒸気 (ガソリンなど) のある所で使用しないでください。火災の原因となります。	本器を分解したり、改造したりしないでください。火災や感電の原因となります。
本器に液体をこぼしたり、金属類を落とし込まないでください。火災や感電の原因となります。そのような場合には、ただちに、電池と USB ケーブルを取り外して、サービスのご案内に記載のお問い合わせ窓口にご相談ください。	万一、本器が破損したり、発煙・異臭が生じた場合は、そのまま使用しないでください。火災の原因となります。発煙・異臭が生じた場合は、ただちに、電池と USB ケーブルを取り外して、サービスのご案内に記載のお問い合わせ窓口にご相談ください。
電池は火の中に入れてたり、充電 (充電式電池は除く)、ショート、加熱、分解などしないでください。電池の破裂、液もれにより、火災やけがの原因となります。	濡れた手で電池に触らないでください。感電の原因となります。
注意 (取り扱いを誤ると、使用者が傷害を負うことが想定される場合、および物理的損害のみの発生が想定される場合)	
本器指定以外の電池を使用しないでください。電池を本器に装填する際は、本器の極性表示 (プラス+とマイナス-) にしたがって正しく装填してください。電池の破損や液漏れにより、火災やけがの原因になったり、周囲を汚損する原因となることがあります。	低電圧以外の電源供給を本体にしないでください。電源供給する際は、安全のためパソコンの USB を介して行ってください。



KONICA MINOLTA

Before using the MULTI GLOSS 268A UNI GLOSS 60A, 60CT, 60S

Please read these instructions before using the instrument

Notes on Instruction Manual and Software

The instruction manual of the instrument and software can be downloaded from the support section in the following URL:
<http://www.konicaminolta.com/instruments/download/>
Please read the instructions carefully before use.

Safety Symbols

The following symbols are used in this manual or the instrument to prevent accidents which may occur as a result of incorrect use of the instrument.

- Denotes a sentence regarding a safety warning or note. Read the sentence carefully to ensure safe and correct use.
- Denotes a prohibited operation. The operation must never be performed.
- Denotes a prohibited operation. Never disassemble the instrument.
- This Symbol indicates direct current(DC).

Safety Precautions

To ensure correct use of this instrument, read the following points carefully and adhere to them. After you have read this manual, keep it in a safe place where it can be referred to any time a question arises. If you pass this instrument to somebody else, make sure to include these instructions.

WARNING (Failure to adhere to the following points may result in death or serious injury)	
Do not use the instrument in places where flammable or combustible gases (gasoline, etc.) are present. Doing so may cause a fire.	Do not disassemble or modify the instrument. Doing so may cause a fire or electric shock.
Take special care not to allow liquid or metal objects to enter the instrument. Doing so may cause a fire or electric shock. Should liquid or metal objects enter the instrument, remove the battery and/or disconnect the USB interface cable immediately, and contact the company where you purchased the instrument.	The instrument should not be operate if it is damaged, or if smoke or odd smells occur. Doing so may result in a fire. In such situations, remove the battery and/or immediately disconnect the USB interface cable, and contact the company where you purchased the instrument.
Do not dispose of batteries in fire, short the terminals, apply heat to them, or disassemble them. Also, do not recharge them. Doing so may cause explosion or heat generation, resulting in fire or injury.	Do not touch the battery with wet hands. Doing so may cause electric shock.
CAUTION (Failure to adhere to the following points may result in injury or in damage to the instrument or other property)	
Do not use batteries other than those specified. When installing batteries in the instrument, make sure that they are correctly oriented according to the (+) and (-) marks. Failure to adhere to these instructions may cause batteries to explode or leakage of electrolytes, resulting in fire, injury or air pollution.	Only devices that meet the requirements for low-voltage safety can be connected to the USB interface.

Authorized Service Facility / お問い合わせ窓口**KONICA MINOLTA, INC.**

(Industrial Instruments)

If you have any questions regarding Konica Minolta's industrial instruments or inquiries about inspection, repair and calibration, please contact the distributor from which your purchase was made or one of the Konica Minolta offices listed below. Some service matters may require transfer of the product to a different facility.

- Konica Minolta Sensing Americas, Inc.
101 Williams Drive, Ramsey, New Jersey 07446, U.S.A.
Phone: (1)-888-473-2656 (in USA), (1)-201-236-4300 (outside USA)
FAX: (1)-201-785-2480
- Konica Minolta Sensing Europe B.V.
Bremen Office (European Service Center)
Utbremer Strasse 90, D-28217 Bremen, Germany
Phone: +49(0)421 526289 46
FAX: +49(0)421 526289 73
- Konica Minolta Sensing Europe B.V.
European Headquarter / BENELUX
Edisonbaan 14-F, 3439MN Nieuwegein, Netherland
Phone: +31(0)30 248-1193
FAX: +31(0)30 248-1280
- Konica Minolta Sensing Europe B.V.
French Office
ZI Paris Nord 2, Le Parc des Reflets, Bât. J, 165 Avenue du Bois de la Pie
BP 59302 Roissy en France, F-95940 Roissy CDG. CEDEX, France
Phone: +33(0)1 80 11 10 71
FAX: +33(0)1 80 11 10 83
- Konica Minolta Sensing Europe B.V.
UK Office
Unit 9 Webster Court, Westbrook Crescent, Gemini Business Park,
Warrington, WA5 8WD United Kingdom
Phone: +44(0)1925 467301
FAX: +44(0)1925 711143
- Konica Minolta Sensing Europe B.V.
Italian Office
Viale Fulvio Testi n. 128
20092 Cinisello Balsamo (MI), Italy
Phone: +39 02849488.00
FAX: +39 02849488.31
- Konica Minolta Sensing Europe B.V.
Swiss Office
Riedstrasse 6, CH-8953 Dietikon, Switzerland
Phone: +41(0)43 322-9800
FAX: +41(0)43 322-9809
- Konica Minolta Sensing Europe B.V.
Nordic Office
Olof Askunds gata 6, SE-421 30 VÄSTRA FRÖLUNDA, Sweden
Phone: +46(0)31 7099464
FAX: +46(0)31 474945
- Konica Minolta Sensing Europe B.V.
Polish Office / Sp. z o.o. Oddział w Polsce
Raclawicka Center, Ul. Skarbowców 23a, 53-025 Wrocław, Poland
Phone: +48(0)71 734 52 11
FAX: +48(0)71 734 52 10
- Konica Minolta (CHINA) Investment Ltd.
SE Sales Division / SE 营业本部
Rm.29A,K Cross Region Plaza, No.899 Lingling Rd., Shanghai 200030, China
200030 上海市零陵路 899 号飞洲国际广场 29A、H、K 室
Phone: +86-021-5489 0202
FAX: +86-021-5489 0005
- Konica Minolta (CHINA) Investment Ltd.
Guangzhou Branch / 广州分公司
Rm.8G, Cheng Jian Building, No.189 West Ti Yu Rd.,
Thian He District, Guangzhou 510620, China
510620 广州市天河区体育西路 189 号城建大厦 8G
Phone: +86-020-3826 4220
FAX: +86-020-3826 4223
- Konica Minolta Sensing Singapore Pte. Ltd.
10, Teban Gardens Crescent, Singapore 608923
Phone: +65 6563-5533
FAX: +65 6560-9721
- コニカミノルタ株式会社
センシング事業本部 CR 推進部 機器サービスグループ
〒590-8551 大阪府堺市堺区大仙西町三丁 91 番地
フリーダイヤル: 0120-890597