

MarCator
1087 BR
1087 BRI

REFERENCE

Bedienungsanleitung
Operating Instructions

3722468

Mahr GmbH
Standort Esslingen
Reutlinger Str. 48, 73728 Esslingen
Tel.: +49 71 9312 600, Fax: +49 71 9312 725
mahr.es@mahr.de, www.mahr.de

0818



Änderungen an unseren Erzeugnissen, besonders aufgrund technischer Verbesserungen und Weiterentwicklungen, müssen wir uns vorbehalten.
Alle Abbildungen und Zahlenangaben usw. sind daher ohne Gewähr.

We reserve the right to make changes to our products, especially due to technical improvements and further developments. All illustrations and technical data are therefore without guarantee.

© by Mahr GmbH

Japanese Radio Law and Japanese Telecommunications Business Law Compliance.
The device is granted pursuant to the Japanese Radio Law (電波法) and the Japanese Telecommunications Business Law (電気通信事業法).
This device should not be modified (otherwise the granted designation number will become invalid).



FCC Compliance

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and the receiver.
- Connect the equipment into an outlet that is on a different circuit from the receiver.
- Consult the dealer or an experienced radio/TV technician for help.

The MarCator 1087BR is labeled with its own FCC ID, N33MC8687R1.

Industry Canada Compliance

This device complies with Industry Canada license exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Under Canadian regulations, this radio transmitter may only operate using an antenna of a type and maximum (or lesser) gain approved for the transmitter by Industry Canada. To reduce potential radio interference to other users, the antenna's gain and location should be so chosen that the equivalent isotropically radiated power (e.i.r.p.) is not more than that necessary for successful communication.

The MarCator 1087BRI is labeled with its own ID, 10315A-MC8687R1.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée sous les deux conditions suivantes: (1) cet appareil ne doit pas causer d'interférences et (2) cet appareil doit accepter toute interférence, y compris celles qui peuvent entraîner un fonctionnement indésirable de l'appareil.

Conformément à la réglementation d'Industrie Canada, le présent émetteur radio peut fonctionner avec une antenne d'un type et d'un gain maximal (ou inférieur) approuvé pour l'émetteur par Industrie Canada. Dans le but d'éduire les risques de brouillage radioélectrique à l'intention des autres utilisateurs, il faut choisir le type d'antenne et son gain de sorte que la puissance isotrope rayonnée équivalente (p.i.r.e.) ne dépasse pas l'intensité nécessaire à l'établissement d'une communication satisfaisante.

Bestimmungsgemäße Verwendung

Die digitale Messuhr 1087 BR / 1087 BRI dient zum Messen von Längemaßen der Produktion, in der Qualitätssteuerung oder in der Werkstatt. Die bestimmungsgemäße Verwendung erfordert das Beachten aller veröffentlichten Informationen zu diesem Gerät sowie der gesetzlichen und innerbetrieblichen Anwendungen. Für hieraus entstehende Schäden haftet der Hersteller nicht. Beachten Sie die für den Einsatzbereich geltenden gesetzlichen und anderenweitigen Vorschriften und Richtlinien.

Diese Messuhren erfüllen die Schutzart IP42 nach DIN EN 60529.

Vor Inbetriebnahme der digitalen Messuhr empfehlen wir Ihnen, die Bedienungsanleitung aufmerksam zu lesen.

Lieferumfang

- Digitale Messuhr (1087 BR / 1087 BRI)
- Batterie CR 2450
- Bedienungsanleitung

Wichtige Hinweise vor Inbetriebnahme

- Um einen langen Nutzen des Messgeräts zu gewährleisten, müssen Verschmutzungen der Messuhr nach Beendigung des Einsatzes mit einem trockenen Tuch entfernt werden.
- Ein verschmutztes Gehäuse mit einem trockenen, weichen Tuch reinigen. Bei starker Verschmutzung mit einem in neutraler Lösungsmittel leicht angefeuchteten Tuch abwischen. Flüssige, organische Lösungsmittel wie Verdünner sind zu vermeiden, da diese Flüssigkeiten das Gehäuse beschädigen können.
- Datenausgang verschließen, wenn dieser nicht benötigt wird.
- Das Messgerät ist in einer Messuhrrhalterung oder entsprechender Vorrichtung zu betreiben. Empfohlen wird eine mit einem Schlitz versehene Halterung mit Aufnahmehöhlung 8H7 mm.
- Reinigen Sie die Messbolzen mit einem in Alkohol angefeuchteten Tuch. Kein Öl auf dem Messbolzen aufbringen!
- Beim Öffnen des Gerätes erhält der Gewährleistungssanspruch.
- Nach Erscheinen des „Low-Bat“ Symbols ist eine bestimmungsgemäße Funktion nicht mehr gewährleistet.

Wir wünschen Ihnen viel Erfolg beim Einsatz Ihrer Messuhr. Falls Sie Fragen haben, stehen Ihnen unsere technischen Berater gerne zur Verfügung.

Sicherheitshinweis



Permitted use

The Digital Indicator 1087 BR / 1087 BRI is to be used to determine length measurements and can be employed in production, quality control and in the workshop.

Permitted use is subject to compliance with all published regulations relating to this product. Any other use is not in accordance with the permitted use.

The manufacturer accepts no liability for damages resulting from improper use. All statutory and other regulations and guidelines applicable to the area of use must be observed.

The Digital Indicators fulfill the protection class IP42 in accordance to DIN EN 60529.

In order to achieve the best use of this Digital Indicator it is very important that you first read these operating instructions.

Contents


- Digital Indicator (1087 BR / 1087 BRI)
- Battery CR 2450
- Operating instructions

Important hints prior to using the Digital Indicator

- Accumulation of dirt on the measuring spindle can impair its movement. Clean measuring spindle with clean cloth (do not oil).
- Clean a dirty housing with a dry, soft cloth. Remove heavy soiling with a cloth wetted with a neutral reacting solvent. Volatile organic solvents like thinners are not to be used, as these liquids can damage the housing.
- Protect the data output opening with the respective cover when not in use.
- The Digital Indicator has to be in an indicator stand or another suitable mounting fixture. We strongly recommend a stand that has a 8H7 mm split mounting bore.
- In order to clean the measuring spindle use a cloth moistened with alcohol. Never apply oil to the measuring spindle!
- Unauthorized opening of the Digital Indicator forfeits the warranty.
- When the „Low-Bat“ symbol appears the intended operation or function can no longer be guaranteed.


We wish you a satisfactory and long service with your Digital Indicator. Should you have any questions regarding the instrument, contact us and we shall be pleased to answer them.

Safety Information



1. Beschreibung

1087 BR / 1087 BRI



1.1 Kennzeichnung und Funktion der Bedientasten

- | | |
|--|---|
| 10 ON/OFF Ein- bzw. Ausschalten des Messgerätes | 10 ON/OFF To switch the instrument ON/OFF |
| ■■■ Messbereichumschaltung der Skalenanzeige | ■■■ Switching the measuring range of the analog display |
| 11 MIN/MAX, MENU-Einstellung | 11 MIN/MAX, MENU-setting mode |
| 12 TOL / SET TOL Toleranzmodus aktivieren, Toleranz einstellen | 12 TOL / SET TOL Active the tolerance mode, set tolerance |
| 13 PRESET / Abrufen des gespeicherten Presetwerts bzw. SET PR-Aktivierung des Preset-Einstellmodus (SET) | 13 PRESET/ Call up the stored preset value resp. SET PR - activation of the Preset-setting mode (SET) |
| 14 RESET Resetting the display | 14 RESET Resetting the display |
| 15 START/STOP der MIN/MAX-Messung | 15 START/STOP of MIN/MAX-measuring |

1.1 Definition and function of the operating keys

10 ON/OFF Ein- bzw. Ausschalten des Messgerätes

■■■ Messbereichumschaltung der Skalenanzeige

11 MIN/MAX, MENU-Einstellung

12 TOL / SET TOL Toleranzmodus aktivieren, Toleranz einstellen

13 PRESET / Abrufen des gespeicherten Presetwerts bzw. SET PR-Aktivierung des Preset-Einstellmodus (SET)

14 RESET Resetting the display

15 START/STOP der MIN/MAX-Messung

10 ON/OFF To switch the instrument ON/OFF

■■■ Switching the measuring range of the analog display

11 MIN/MAX, MENU-setting mode

12 TOL / SET TOL Active the tolerance mode, set tolerance

13 PRESET/ Call up the stored preset value resp. SET PR - activation of the Preset-setting mode (SET)

14 RESET Resetting the display

15 START/STOP of MIN/MAX-measuring



Technische Daten

Messsystem	induktiv	Measuring system	inductive
Anzeige	LCD, Zifferhöhe 8,5 mm	Display	LCD, height of digits 8,5 mm
Batterie	Renate CR 2450, 560 mAh	Battery	Renate CR 2450, 560 mAh
	Bestell-Nr.: 4884464	Order no.:	approx. 3 years
Betriebstemperatur	+10° C bis +40° C	Lifetime of battery *	(2000 hours/year)
Lagertemperatur	-10° C bis +60° C	Operating temperature	+10° C to +40° C
Datenausgang	RS232C kompatibel über Interfacekabel mit Opto-koppler, Digtigitar oder USB	Storage temperature	-10° C to +60° C
	Funkfrequenzstelle **	Data output	RS232C compatible via interface cable with Opto-coupler, Digtigitar or USB wireless interface
RF Frequenz Band	Kanal 1 2409 MHz, Kanal 2 2439 MHz, Kanal 3 2475 MHz	RF Frequency band	Channel 1 2409 MHz, Channel 2 2439 MHz, Channel 3 2475 MHz
Funkstrecke	typischer Bereich 5-10 m abhängig vom Umfeld und Empfänger	Communication range	typical 5-10 m depending on specific environment and receivers
Gewicht	135 g	Weight	135 g

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis zu Störungen und Reichweite: **
Das eingesetzte Funksystem arbeitet in 2,4 GHz-Bereich, der auch von anderen Funkdiensten genutzt wird.

Daher kann es durch Geräte, die auf der gleichen bzw. benachbarten Frequenz arbeiten, zu Einschränkungen des Betriebs und der Reichweite kommen.

Zudem können Hochfrequenzstörungen aller Art zu Einschränkungen des Betriebs führen.

* reduziert sich beim Betreiben der Funkfrequenzstelle

** bei Modell mit Funkfrequenzstelle

The wireless system used operates in the 2.4 GHz band, which is also used by other wireless systems.

This means that devices operating on the same or an adjacent frequency can lead to restrictions in terms of operation and range.

Furthermore all types of radio frequency interference can lead to restrictions in terms of operation.

Hinweis zu Störungen und Reichweite: **
The wireless system used operates in the 2.4 GHz band, which is also used by other wireless systems.

This means that devices operating on the same or an adjacent frequency can lead to restrictions in terms of operation and range.

Furthermore all types of radio frequency interference can lead to restrictions in terms of operation.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis:
Digital indicators that have a wireless interface, the RS232C is only active when the wireless interface is deactivated.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis:
Digital indicators that have a wireless interface, the RS232C is only active when the wireless interface is deactivated.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis:
Digital indicators that have a wireless interface, the RS232C is only active when the wireless interface is deactivated.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis:
Digital indicators that have a wireless interface, the RS232C is only active when the wireless interface is deactivated.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis:
Digital indicators that have a wireless interface, the RS232C is only active when the wireless interface is deactivated.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis:
Digital indicators that have a wireless interface, the RS232C is only active when the wireless interface is deactivated.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

Hinweis:
Digital indicators that have a wireless interface, the RS232C is only active when the wireless interface is deactivated.

Hinweis:
Bei digitalen Messuhren mit Funkfrequenzstelle ist die RS232C nur aktiv, wenn die Funkfrequenzstelle deaktiviert ist.

3.2 Einstellen der Funkparameter *

- Taste MENU lang drücken
- => Anzeige „d ----“ bzw. z.B. „d 01001“, wenn eine Adresse bereits zugewiesen ist, oder „d OFF“ erscheint im Display.
- Durch kurzen Tastendruck auf Taste ON/OFF kann die Funkfunktion deaktiviert „d OFF“ bzw. aktiviert werden. Anzeige „d ----“ bzw. zugewiesene Adresse z.B. „d 01001“.

3.2b Adresse zuweisen

- > Anzeige zeigt eine alte Adresse, z.B. d 01123
- Taste PRESET kurz drücken
- > Anzeige zeigt „d ----“
- Taste ▲ kurz drücken
- > Symbol „d“ blinkt. Wird das Funksymbol eingeschaltet, so ist der Maßnahm eine Adresse durch die Software MarCom zugewiesen worden und wird im Display angezeigt.
- Durch kurzen Druck auf Taste ON/OFF kann die Adresszuweisung gestoppt werden und mit kurzen Druck auf Taste ▲ wieder fortgesetzt werden.
- Weiter mit Taste ▶

3.2c Funkanwendung einstellen

Als Werkseinstellung ist Kanal CH 01 eingestellt.

Hinweis: Eine Umstellung auf Kanal 2 oder 3 ist nur erforderlich, wenn es zu Konflikten mit anderen Geräten kommt, die die Frequenz 2,4 GHz nutzen.

Hinweis: Die Kanalnummer muss mit der Kanalnummer in der Software MarCom übereinstimmen!

- > Einstellung des Kanals mit Taste ▲
- Weiter mit Taste ▶

3.2d ECO-Modus

Als Werkseinstellung ist der ECO-Modus ausgeschaltet.

Hinweis: Im ECO Modus wird die Übertragungsgeschwindigkeit reduziert, dadurch sind schnelle Übertragungsintervalle <7 Sekunden nicht empfehlenswert bzw. nicht möglich.

Sollte der ECO Modus aktiviert sein, so muss dieser auch in der Software MarCom im i-wi Funktionen aktiviert werden!

- > ECO-Modus aktivieren bzw. deaktivieren (Pfeil-▲ drücken)
- weiter mit Taste ▶

Hinweis: Nach Änderungen wie unter 3.2c und 3.2d beschrieben, muss evtl. die Verbindung wieder hergestellt werden.

* Hinweis: Die beschriebenen Funktionen unter „Punkt 3.2 Einstellung der Funkparameter“ sind nur bei digitalen Messuhren mit i-wi-Funktion möglich!

3.3 Einstellfunktionen

3.3a) mm/inch / Umschaltung der Maßeinheit

- Taste MENU lang drücken:
- => Anzeige unit erscheint im Display
- Taste ▲ kurz drücken:
- > Symbol inch erscheint im Display
- > Maßeinheit inch aktiv
- > Gewünschte Maßeinheit auswählen
- Weiter mit Taste ▶

3.3b) Einstellung Ziffernschrift

Hinweis: Nur für Geräte mit umschaltbarem Ziffernschrift

- > Aktueller Ziffernschrift erscheint in der Anzeige (z. B. 0.001)
- Taste ▲ kurz drücken
- > Ziffernschrift ändert sich mit jedem Tastendruck (0.0005/0.001/0.002/0.005/0.01 mm) bzw. (.00002/.00005/.0001/.0002/.0005 inch)
- Weiter mit Taste ▶

3.3c) ▲▼ / Messrichtungsumschaltung

- > Symbol ▲ erscheint in der Anzeige. Positive Zählrichtung bei hineingehendem Tastendruck
- > Taste ▲ kurz drücken
- > Symbol ▼ erscheint in der Anzeige. Negative Zählrichtung bei hineingehendem Tastenblöcken.
- Weiter mit Taste ▶

3.3d) Individuelle Tastatursperre

- Sperren und Lösen der jeweiligen Taste über kurzen bzw. langen Tastendruck. Setzen der Funktion über der Taste durch kurzen Tastendruck, unter der Taste durch langen Tastendruck.
- Zum Verlassen Taste ON/OFF kurz drücken. Wert wird gespeichert.
- Aktivieren/- Deaktivieren der Tastatursperre
- > Tol. und ON/OFF gleichzeitig kurz drücken
- > Einstellung für Auto OFF erscheint in der Anzeige.

Hinweis: Wenn keine Änderungen erfolgen, weiter mit Taste ▶

3.3e) Auto OFF einstellen

- > Taste ▲ kurz drücken
- > 1. Stelle der Eingabe blinkt
- > Taste ▶ kurz drücken
- > 2. Stelle der Eingabe blinkt
- > Taste ▲ kurz drücken
- > Eingabewert erhöht sich bei jedem Tastendruck (0, 1, 2 ... 9), max. 999 Minuten einstellbar
- > Taste ON/OFF kurz drücken
- > Wert wird gespeichert

Hinweis: Wenn keine Änderungen erfolgen, weiter mit Taste ▶

3.3f) Faktoreinstellung

- > Taste ▲ kurz drücken
- > 1. Stelle der Eingabe blinkt
- > Eingabewert erhöht sich bei jedem Tastendruck (0, 1, 2 ... 9)
- > Taste ▶ kurz drücken
- > 2. Stelle der Eingabe blinkt
- > Taste ON/OFF kurz drücken
- > Wert wird gespeichert. FA-SET erscheint im Display

Hinweis: Wenn keine Änderungen erfolgen, weiter mit Taste ▶

3.3g) Einstellung Datenausgang (siehe 5.1)

- > Out - erscheint in der Anzeige (Daten werden ohne Einheit gesendet)
- > Taste ▲ kurz drücken
- > Out mm/inch erscheint in der Anzeige (Daten werden mit Einheit gesendet)

Weiter mit Taste ▶

3.2) Einstellen der Funkparameter *

3.2a) Activate/Deactivate Wireless

- Press and hold the MENU key
- => When an address has already been allocated, in the display will either appear „d ----“ e.g., „d 01001“, or „d OFF“.
- Press and release the ON/OFF key to deactivate the wireless function, in the display will appear „d OFF“ and/or activated, „d ----“ or the allocated address „d 01001“ will appear in the display.

3.2b) Allocate an Address

- > In the display an old address appears, for example d 01123
- Press and release the PRESET key
- > d ---- appears in the display
- > Continue with the ▲ key
- > The symbol „Wireless“ will flash. If the wireless symbol is permanently shown, the indicator has been allocated an address via the MarCom software; this address will appear in the display.
- By briefly pressing the ON/OFF key the address allocation can be stopped, to continue with the allocation press the ▲ key.
- Continue with the ▶ key

3.2c) Set a Wireless Channel

In the factory settings the channel CH 01 is preset.

Note: Switching to channel 2 or 3 is only required, when there is a conflict with other devices that use channels 2 or 3.

Note: The channel number must correspond to the channel number in the MarCom software!

- > Set the channel with the ▲ key
- Continue with the ▶ key

3.2d) ECO mode

In the factory settings the ECO mode is deactivated.

Note: In the ECO mode the transmission speed is reduced, therefore fast transmission intervals <7 seconds are not recommended and/or possible.

If the ECO mode should be activated, this can also be activated in the MarCom software on the i-wi measuring instrument!

- > To activate/deactivate the ECO mode (Press arrow ▲ key)
- Continue with the ▶ key

Note: After the changes made in point 3.2c and 3.2d, the connection may have to be reestablished

* Note: The described functions in „point 3.2 Setting the Wireless Parameter“ are only possible with Digital Indicators with the i-wi function!

3.3 Setting functions

3.3a) mm/inch / Changing the unit of measurement

- Press and hold MENU key:
- > The symbol unit will appear in the display:
- Briefly press the ▲ key
- > Unit of measurement is set to inch
- Select the required unit of measurement
- Continue with the ▶ key

3.3b) Setting the Resolution

Note: Only available for digital indicators that have a switchable resolution

- > Actual resolution appears in the display (e.g. 0.001)
- Briefly press the ▲ key
- > Resolution changes each time the key is pressed (0.0005/0.001/0.002/0.005/0.01 mm) resp. (.00002/.00005/.0001/.0002/.0005 inch)
- Continue with the ▶ key

3.3c) ▲▼ / Changing the measuring direction

- > The symbol ▲ appears in the display. Positive counting direction, value will increase when the spindle moves upwards
- Briefly press the ▲ key
- > The symbol ▼ appears in the display. Negative counting direction, value will decrease when the spindle moves upwards
- Continue with the ▶ key

3.3d) Individual Key Lock

- To lock and unlock individual keys. Press the respective key either with a short (press & release) or long (press & hold) on the key for the function below the key press and hold the respective key.
- To exit, briefly press the ON/OFF key. Value will be stored
- Activate-/ deactivate the individual key lock
- Press the Tol and ON/OFF key simultaneously => The setting of the Auto OFF appears in the display.

Note: When there are no further adjustments are to be made, press the ▶ key

3.3e) Set and adjust the Auto OFF

- > Shortly press the ▲ key
- > The 1st input position will flash
- > Shortly press the ▶ key
- > The 2nd input position will flash
- > Shortly press the ▲ key
- > The digit will increase, each time the key is pressed (0, 1, 2 ... 9), max. 999 minutes selectable
- > Shortly press the ON/OFF key
- > Value will be stored

Note: When there are no further adjustments are to be made, press the ▶ key

3.3f) Factor Setting

- > Shortly press the ▲ key
- > The 1st input position will flash
- > Shortly press the ▲ key
- > The digit will increase, each time the key is pressed (0, 1, 2 ... 9)
- > Shortly press the ▶ key
- > The 2nd input position will flash
- > Shortly press the ON/OFF key
- > Value will be stored. FA-SET appears in the display

Note: When there are no further adjustments are to be made, press the ▶ key

3.3g) Setting the Data Output (see 5.1)

- > Out - appears in the display (data will be sent without the measuring unit)
- > Briefly press the ▲ key
- > Out mm/inch appears in the display (data is sent with the measuring unit)

Continue with the ▶ key

3.2) Setting the Wireless Parameter *

3.2a) Activate/Deactivate Wireless

- Press and hold the MENU key
- => When an address has already been allocated, in the display will either appear „d ----“ e.g., „d 01001“, or „d OFF“.
- innerhalb 5 Sek. Taste PRESET kurz drücken und Rücksetzen auf Werkseinstellung, Einstellmenü wird verlassen.

Hinweis: Wenn keine Änderungen erfolgen, weiter mit Taste ▶

3.2b) Allocate an Address

- > In the display an old address appears, for example d 01123
- Press and release the PRESET key
- > d ---- appears in the display
- > Continue with the ▲ key
- > The symbol „Wireless“ will flash. If the wireless symbol is permanently shown, the indicator has been allocated an address via the MarCom software; this address will appear in the display.
- By briefly pressing the ON/OFF key the address allocation can be stopped, to continue with the allocation press the ▲ key.
- Continue with the ▶ key

3.2c) Set a Wireless Channel

In the factory settings the channel CH 01 is preset.

Note: Switching to channel 2 or 3 is only required, when there is a conflict with other devices that use channels 2 or 3.

Note: The channel number must correspond to the channel number in the MarCom software!

- > Set the channel with the ▲ key
- Continue with the ▶ key

3.2d) ECO mode

In the factory settings the ECO mode is deactivated.

Note: In the ECO mode the transmission speed is reduced, therefore fast transmission intervals <7 seconds are not recommended and/or possible.

If the ECO mode should be activated, this can also be activated in the MarCom software on the i-wi measuring instrument!

- > To activate/deactivate the ECO mode (Press arrow ▲ key)
- Continue with the ▶ key

Note: After the changes made in point 3.2c and 3.2d, the connection may have to be reestablished

* Note: The described functions in „point 3.2 Setting the Wireless Parameter“ are only possible with Digital Indicators with the i-wi function!

3.3 Setting functions

3.3a) mm/inch / Changing the unit of measurement

- Press and hold MENU key:
- > The symbol unit will appear in the display:
- Briefly press the ▲ key
- > Unit of measurement is set to inch
- Select the required unit of measurement
- Continue with the ▶ key

3.3b) Setting the Resolution

Note: Only available for digital indicators that have a switchable resolution

- > Actual resolution appears in the display (e.g. 0.001)
- Briefly press the ▲ key
- > Resolution changes each time the key is pressed (0.0005/0.001/0.002/0.005/0.01 mm) resp. (.00002/.00005/.0001/.0002/.0005 inch)
- Continue with the ▶ key

3.3c) ▲▼ / Changing the measuring direction

- > The symbol ▲ appears in the display. Positive counting direction, value will increase when the spindle moves upwards
- Briefly press the ▲ key
- > The symbol ▼ appears in the display. Negative counting direction, value will decrease when the spindle moves upwards
- Continue with the ▶ key

3.3d) Individual Key Lock

- To lock and unlock individual keys. Press the respective key either with a short (press & release) or long (press & hold) on the key for the function below the key press and hold the respective key.
- To exit, briefly press the ON/OFF key. Value will be stored
- Activate-/ deactivate the individual key lock
- Press the Tol and ON/OFF key simultaneously => The setting of the Auto OFF appears in the display.

Note: When there are no further adjustments are to be made, press the ▶ key

3.3e) Set and adjust the Auto OFF

- > Shortly press the ▲ key
- > The 1st input position will flash
- > Shortly press the ▶ key
- > The 2nd input position will flash
- > Shortly press the ▲ key
- > The digit will increase, each time the key is pressed (0, 1, 2 ... 9), max. 999 minutes selectable
- > Shortly press the ON/OFF key
- > Value will be stored

Note: When there are no further adjustments are to be made, press the ▶ key

3.3f) Factor Setting

- > Shortly press the ▲ key
- > The 1st input position will flash
- > Shortly press the ▲ key
- > The digit will increase, each time the key is pressed (0, 1, 2 ... 9)
- > Shortly press the ▶ key
- > The 2nd input position will flash
- > Shortly press the ON/OFF key
- > Value will be stored. FA-SET appears in the display

Note: When there are no further adjustments are to be made, press the ▶ key

3.3g) Setting the Data Output (see 5.1)

- > Out - appears in the display (data will be sent without the measuring unit)
- > Briefly press the ▲ key
- > Out mm/inch appears in the display (data is sent with the measuring unit)

Continue with the ▶ key

3.3) Werkseinstellung

- Taste ▲ kurz drücken
- > FA-SET blinkt in der Anzeige max. 5 Sek.
- innerhalb 5 Sek. Taste PRESET kurz drücken und Rücksetzen auf Werkseinstellung, Einstellmenü wird verlassen.

Hinweis: Wenn keine Änderungen erfolgen, weiter mit Taste ▶

3.4 Messfunktionen

3.4a) TOL:Toleranz aktivieren/ deaktivieren

- > Taste TOL kurz drücken
- > Toleranzmarken in der Skalenanzeige und Symbol „TOL“ erscheinen in der Anzeige. Die Toleranzmarken bei Unterschreiten wird durch Pfeile in der Anzeige angezeigt. Beleuchtet befindet sich die Marke des aktuellen Messwerts direkt auf einer der Toleranzmarken der Skalenanzeige, so blinkt die entsprechende Marke.

Hinweis: Folgende Funktion ist gesperrt:

3.4b) MIN / MAX

Dynamische Messfunktion auswählen:

- > Taste MAX/MIN kurz drücken
- > Symbol MIN erscheint in der Anzeige (Minimalwertfassung z.B. bei Bohrungsmeßung mit 2-Punkt-Innenmessgeräten)
- > Durch kurzes Betätigen der blauen START/STOP-Taste wird die MIN-Funktion aktiviert (A) (MIN Symbol blinkt in der Anzeige).

Beim Messen wird in der Ziffern- und Skalenanzeige der niedrigste Wert angezeigt und gespeichert (Schleppzeigerfunktion) (B)

- > Durch kurzes Betätigen der blauen START/STOP-Taste wird die MIN-Funktion deaktiviert und der erreichte Wert im Display gespeichert (MIN Symbol blinkt nicht mehr in der Anzeige) (C).

Gleichzeitig wird der Messwert über RS 232C oder i-wi-Funkschnittstelle übertragen.

- > Durch erneutes Betätigen der START/STOP-Taste wird die MIN-Funktion wieder für die nächste Messung aktiviert.
- > Taste MAX/MIN nochmals kurz drücken
- > Symbol MAX erscheint in der Anzeige (Maximalwertfassung)
- > Durch kurzes Betätigen der blauen START/STOP-Taste wird die MAX-Funktion aktiviert (MAX Symbol blinkt in der Anzeige).

Beim Messen wird in der Ziffern- und Skalenanzeige der niedrigste Wert angezeigt und gespeichert (Schleppzeigerfunktion)

- > Durch kurzes Betätigen der blauen START/STOP-Taste wird die MAX-Funktion deaktiviert und der erreichte Wert im Display gespeichert und die Daten übertragen (MAX Symbol blinkt nicht mehr in der Anzeige).

Gleichzeitig wird der Messwert über RS 232C oder i-wi-Funkschnittstelle übertragen.

3.4c) ▲▼ Messbereichsumschaltung der Skalenanzeige

- > Press and hold MENU key:
- > The symbol unit will appear in the display:
- Briefly press the ▲ key
- > Unit of measurement is set to inch
- Select the required unit of measurement
- Continue with the ▶ key

3.4d) ▲▼ Messbereichsumschaltung der Skalenanzeige

- > Press and hold MENU key:
- > The symbol unit will appear in the display:
- Briefly press the ▲ key
- > Unit of measurement is set to inch
- Select the required unit of measurement
- Continue with the ▶ key

3.4e) ▲▼ Messbereichsumschaltung der Skalenanzeige

- > Press and hold MENU key:
- > The symbol unit will appear in the display:
- Briefly press the ▲ key
- > Unit of measurement is set to inch
- Select the required unit of measurement
- Continue with the ▶ key

3.4f) PRESET eingeben

- > Taste PRESET/SET lang drücken
- > Symbol PRESET erscheint in der Anzeige, +/ - blinkt. SET-Modus ist aktiviert
- > Taste ▲ kurz drücken
- > Vorzeichen (+/-) wechselt bzw. Anzeigestelle erhöht sich bei jedem Tastendruck (0, 1, 2 ... 9)
- > Taste ▶ kurz drücken
- > Nächste Anzeigestelle blinkt
- > Zum Setzen der nächsten Anzeigestelle den Vorgang wiederholen.
- > Taste PRESET kurz drücken
- > Symbol PRESET wird ausgeblendet. Eingegebener PRESET-Wert wird gespeichert und gleichzeitig aktiviert

Hinweis: PRESET-Wert bleibt auch beim Ausschalten erhalten.

PRESET aktivieren

- > Taste PRESET kurz drücken
- > Gespeicherter PRESET-Wert erscheint als aktueller Wert in der Anzeige. Gleichzeitig wird das ABS-Symbol aktiviert

Hinweis: Achten Sie darauf, dass die Messrichtung (3.3b) für Ihre Anwendung richtig gesetzt wurde.

3.4g) Setting the Data Output (see 5.1)

- > Out - appears in the display (data will be sent without the measuring unit)
- > Briefly press the ▲ key
- > Out mm/inch appears in the display (data is sent with the measuring unit)

Continue with the ▶ key

3.3) Werkseinstellung

- > FA-SET blinkt in der Anzeige max. 5 Sek.
- > Reset to factory settings. The setting menu is exited.

Hinweis: When there are no further adjustments are to be made, press the ▶ key or press the MENU key.

3.4) Measuring functions

3.4a) TOL: Activate/ deactivate Tolerance

- > Press and release the TOL key
- > Tolerance markers in the analog display and the symbol TOL in the digital display will appear. When the tolerance limit is exceeded, an arrow will appear in the display. If the marker representing the actual measuring value is directly on the tolerance marker shown in the analog display the appropriate marker will flash.

Hinweis: The following function is blocked:

3.4b) MIN / MAX

Select dynamic measuring functions:

- > Press and release the MAX/MIN key
- > The symbol MIN will appear in the display (Acquisition of the minimum value, for example by measuring a bore hole with a 2-point measuring instrument)
- > To confirm, press and release the blue START/STOP-key. The MIN function is thus activated (A) (MIN symbol will flash in the display).

When measuring the lowest value will appear in both the analog and digital displays, this value will also be saved (Drag Indicator Function) (B).

- > To deactivate the MIN-function, press and release the blue START/STOP-key, the acquired value will appear in the display (MIN symbol no longer flashes in the display) (C).

The measured values will be simultaneously transferred via RS232C or i-wi wireless interface.

- > By pressing the START/STOP key again, the MIN function is activated for the next measurement.
- > Press and release the MIN/MAX key
- > Symbol MAX will appear in the display (Acquisition of the maximum value)
- > Press and release the blue START/STOP-key, the MAX function is now activated (MAX symbol will flash in the display).

When measuring the lowest value will appear in both the analog and digital displays, this value will also be saved (Drag Indicator Function)

- > To deactivate the MAX-function, press and release the blue START/STOP-key, the acquired value will appear in the display and the data are transferred (MAX symbol no longer flashes in the display).

The measured values will be simultaneously transferred via RS232C or i-wi wireless interface. By pressing the START/STOP key again, the MAX function is activated for the next measurement.

- > Once again press and release the MIN/MAX key
- > The Digital Indicator returns to being in Normal mode

Note: The following functions are blocked during the acquisition of extreme values:

3.4d) PRESET Enter PRESET

- > Press and hold the PRESET/SET key
- > The symbol PRESET will appear in the display and the symbol +/- will flash; this indicates that the SET mode is activated
- > Press and release the - key
- > The +/- sign changes and the digit will increase with each key press (0, 1, 2 ... 9)
- > Press and release the